





BC AUCTION VEHICLE & EQUIPMENT INSPECTION REPORT

Inspected By: Joe K Exterior Cleaned by: _____ Interior Cleaned by: _____ De-Decal by: _____

Unit #: Kubota

Year: _____

Manufacture: Kubota

Model and Trim: RTY X1100C

VIN #: _____

Exterior Color: Orange

Interior Color: Black

Has Keys: Yes No

Lockable: Yes No

Vehicle Runs: Yes No

Test Driven: Yes No

Driver: Joe K

Vehicle Charges (Office Use Only)

Amber / Spotlight Removal: _____ Piece/s

Battery Replacement: _____ Piece/s

General Labor Hours: _____ Hour/s

Decal Removal: _____ S / M / L

Report Verified By: _____

DRIVETRAIN:

CIRCLE / FILL OUT ALL APPLICABLE

Battery: Dead Fair New
Drive: Awd Fwd Rwd 4x4
Mechanical: Knocks Rattles Squeals Whines
Mileage: N/A Km Mi
Engine Size: _____ Litres
Engine Hours: 1474 Total Hours
Fuel Type: Gas Diesel Electric Propane Hybrid
Transmission: Automatic Standard _____ Overdrive
speeds

Illuminated Dash Lights

Air Bag Light ☐ Anti-Lock Brakes ☐
Brake Warning ☐ Check Engine Light ☐
Coolant Light ☐ Service Light ☐
Stability Control ☐ Tire Pressure System ☐
Traction Control ☐ 4x4 / AWD Fault ☐
Other (Specify on Reverse) ☐

none

EXTERIOR:

CIRCLE / FILL OUT ALL APPLICABLE

Body Style: 2 Door 3 Door 4 Door X Cab Crew Cab
Box Style: Short Standard Long
Tires: Good Fair Poor Studded
Windshield: Chipped Cracked Scuffed Good
Bolt Holes: Body Roof
Air Brakes: Yes No
Jack: Yes No
Spare: Yes No

Deck and/or Box Dimensions

Total Exterior Length: _____ Inches
Total Exterior Width: _____ Inches
Total Exterior Height: _____ Inches
Wheelbase: _____ Inches
Total Interior Length: _____ Inches
Total Interior Width: _____ Inches
Total Interior Height: _____ Inches

INTERIOR:

CIRCLE / FILL OUT ALL APPLICABLE

Screw Holes: Console Dash Floor Headliner
Seat Material: Fabric Leather Vinyl
Floor Material: Carpet Metal Rubber
Interior Trim: Broken Loose Missing
Interior Stains: Seats Floor Headliner Trim

Electric Winch

Brand: _____
Capacity: _____
Controller: Yes No
Functional / Tested: Yes No

Tested Options		Untested Options & Equipment	
Air Conditioning ☒	Power Mirrors ☐	Air Bag ☐	Navigation ☐
Working: <u>Yes</u> or <u>No</u>	Working: <u>Yes</u> or <u>No</u>	Bed Liner ☒	Power Take-Off Shaft ☐
Amber Light/s ☒	Power Trunk/Tailgate ☐	Bed Slide ☐	Rear Window Defrost ☐
Working: <u>Yes</u> or <u>No</u>	Working: <u>Yes</u> or <u>No</u>	Block Heater ☐	Roof Rack ☐
Backup Camera ☐	Power Windows ☐	Canopy ☐	Tilt Steering ☐
Working: <u>Yes</u> or <u>No</u>	Working: <u>Yes</u> or <u>No</u>	Cruise Control ☐	Toolbox ☐
Delay Wipers ☐	Power Sunroof ☐	Headache Rack ☐	Tonneau Cover ☐
Working: <u>Yes</u> or <u>No</u>	Working: <u>Yes</u> or <u>No</u>	Heated Mirrors ☐	Trailer Brake Controller ☐
Power Door Locks ☐	Pedal Adjustment ☐	Heated Seats ☐	Trailer Hitch ☐
Working: <u>Yes</u> or <u>No</u>	Working: <u>Yes</u> or <u>No</u>	Other (Specify Below) ☐	
Power Driver Seat ☐	Radio/Stereo ☒		
Working: <u>Yes</u> or <u>No</u>	Working: <u>Yes</u> or <u>No</u>		
Power Passenger Seat ☐	Rear Wiper ☐		
Working: <u>Yes</u> or <u>No</u>	Working: <u>Yes</u> or <u>No</u>		

CIRCLE ALL APPLICABLE:

VISIBLE DENTS, SCRATCHES, PAINT CHIPS AND RUST ALL OVER ☐

Hood	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	Rust Spots	Paint Chips	Cracked
Grill	Scratches	<u>Scuffs</u>	Dent	Large Dents	Multiple Dents	<u>Rust Spots</u>	<u>Paint Chips</u>	Cracked
Front Bumper	Scratches	<u>Scuffs</u>	Dent	Large Dents	Multiple Dents	<u>Rust Spots</u>	<u>Paint Chips</u>	Cracked
Drivers Fender	Scratches	<u>Scuffs</u>	Dent	Large Dents	Multiple Dents	<u>Rust Spots</u>	<u>Paint Chips</u>	Cracked
Drivers Front Door	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	Rust Spots	Paint Chips	Cracked
Drivers Rear Door	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	Rust Spots	Paint Chips	Cracked
Drivers Quarter/Box Side	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	<u>Rust Spots</u>	<u>Paint Chips</u>	<u>Cracked</u>
Drivers Rocker	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	<u>Rust Spots</u>	<u>Paint Chips</u>	<u>Cracked</u>
Trunk/Tailgate	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	<u>Rust Spots</u>	<u>Paint Chips</u>	<u>Cracked</u>
Rear Bumper	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	<u>Rust Spots</u>	<u>Paint Chips</u>	<u>Cracked</u>
Passenger Rocker	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	<u>Rust Spots</u>	<u>Paint Chips</u>	<u>Cracked</u>
Pass Quarter/Box Side	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	<u>Rust Spots</u>	<u>Paint Chips</u>	<u>Cracked</u>
Passenger Rear Door	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	Rust Spots	Paint Chips	Cracked
Passenger Front Door	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	Rust Spots	Paint Chips	Cracked
Passenger Fender	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	Rust Spots	Paint Chips	Cracked
Roof	Scratches	Scuffs	Dent	Large Dents	Multiple Dents	Rust Spots	Paint Chips	Cracked

This vehicle is not safe for use. Rusted frame, not fixable. Dangerous.

PARTS ONLY!

Joe K





KUBOTA

4x4

Extra Duty
IRS

16500



KUBOTA



